		South	nern Star 2019 Pla			ed Service Outage Dashboard	Historical Average ID3 Sch	eduled Volume
Work Activity						Operational Capacity Information		
Status	Projected Start Date	Projected Return to Normal Date	Location(s)	Type of Work	Мар	Capacity After Reduction	% Reduction from Normal Operational Capacity	Constraint Area(s)
	December 4, 2019	December 5, 2019	Blackwell C/S	Station ESD		320,000 Dth/d Blackwell CS (Location 445511)	49% Reduction - Blackwell CS (Location 445511)	SB, CB, BE, SE, OK Other